



## Certificate of Compliance

Certificate Number: 0131-10-18-CYC-TD

Type of Certification: Annual monitoring audit – Full certificate


For the recycling plant:

### **bage plastics GmbH**

Recycling plant: Hainbach 14, **4493 Wolfern**

Extrusion: Eisenstraße 96, **4502 St. Marien**  
**Austria**

Process	Input material	Presentation	Nominal capacity (t/a)	Post-consumer material accepted for recycling in previous 12 months (t)	Output of recycling process	Post-consumer recycled output (t)	Pre and post-consumer recycled output (t)	Level of traceability (1 to 2)	Washed material
Mechanical recycling/ final recipient	WEEE (mixture of PP – rigid, PS – rigid, ABS – rigid, PC – rigid)	Bulk material (shredded)	14,000	11,373	PP-, PS-, ABS-, ABS/PC-pellets/ grinding stock	8,393	8,529	2	Y

Audited by: Thomas Döpelheuer	<b>Auditor's logo:</b>  cyclos GmbH Westerbreite 7 49084 Osnabrück, GERMANY Telefon: +49 541 77080-0 Fax: +49 541 77080-99 thomas.doepelheuer@cyclos.de
Date of audit: 14/09/2017	
Period of evaluation: 09/2017 to 08/2018	
Period of validity: from 06/10/2017 to 05/10/2018	

The recycling process and associated management systems of the aforementioned company for the waste plastic and site shown has been audited and have met the required standards for certification under the EuCertPlast Scheme for European Plastic Recyclers.

This plant is the last recipient of plastic waste and produced products.

Osnabrück, 06 October 2017

Thomas Döpelheuer



Publicly certified expert on packaging disposal, appointed by the chamber of commerce and industry  
Competent: Chamber of commerce and industry Osnabrück – Emsland – Grafschaft Bentheim

EuCertPlast c/o EuPR, Avenue de Cortenbergh 71, 1000 Brussels, BELGIUM

[www.eucertplast.eu](http://www.eucertplast.eu)